

May 7, 1987


TO: File

FROM: Frank J. Filas, Reclamation Engineer

RE: Site Inspection, M/037/012, Pandora Mine

On April 14, 1987, Frank Filas drove by Atlas's Pandora Mine. Other commitments precluded making a site inspection at that time. It appears that the old waste dumps will be difficult to reclaim due to their size and lack of stockpiled topsoil.

clj
1117R/44



M/037/012, Pandora Mine 4-14-87

Looking down at Pandora
Mine from UMETCO's LaSal
Mine.

M/037/012, Pandora 4-14-87

Atlas had a small crew on
site (probably doing rehabilitation
work underground)

M/037/012, Pandora 4-14-87